













P Series
P6 Fault Code

A "P6" fault code indicates that the indoor unit's pipe or coil thermistor has detected a temperature of 5 degrees F. or lower and has shut the system down to protect the indoor coil from freeze damage. This could be caused from a number of things such as dirty air filters, a faulty indoor blower motor, low refrigerant charge, or even a thermistor that is out of calibration.









